

Notice to Skippers no. 10/07.02.2020

regarding the modifications of the luminous floating and coastal signalling

For the information of the skippers of vessels and convoys, we let you know the modifications operated at the luminous floating and coastal signaling

Sulina Bar

1. Hm 90+00 Electric Red Buoy missing since 07.02.2020
2. Hm 87+00 Electric Green Buoy missing since 07.02.2020
3. Hm 85+00 Electric Green Buoy missing since 07.02.2020
4. Hm 83+00 Electric Green Buoy missing since 07.02.2020

General Manager
Sorin Crețu

Chief Engineer
Corneliu Carp

Chief of Hydro-technical, Hydrology
& Danube Commission Department
Mihai Popescu - Teclu

Drafted:C.C./ 1 ex.07.02.2020
Translated: A.R. / 07.02.2020

F1 P.O.8.5.1-24