

Notice to Skippers no. 14/19.02.2020

regarding the modifications of the luminous floating and coastal signalling

For the information of the skippers of vessels and convoys, we let you know the modifications operated at the luminous floating and coastal signaling

River Sector of the Danube

1. Km 285+800 red buoy missing since 16.02.2020

General Manager
Dumitru Dorian

Chief Engineer
Corneliu Carp

Chief of Hydro-technical, Hydrology
& Danube Commission Department
Mihai Popescu - Teclu

Drafted: C.C./ 1 ex.19.02.2020

Translated: A.R. /19.02.2020