

Notice to Skippers no. 140 /22.10.2019

regarding the modifications of the luminous floating and coastal signalling

For the information of the skippers of vessels and convoys, we let you know the modifications operated at the luminous floating and coastal signaling

River Sector of the Danube

1. Km 191+500 green buoy missing since 22.10.2019
2. Km 239+000 Electric Red Green Buoy missing since 21.10.2019

The present Notice to Skippers modifies the following NtS:

- NtS.4/ 14.01.2019 pos.4
- NtS.137 /25.09.2018 pos.3

General Manager
Dumitru Dorian

Chief Engineer
Corneliu Carp

Chief of Hydro-technical, Hydrology
& Danube Commission Department
Mihai Popescu - Teclu

Drafted: C.C./ 22.10.2019
Translated: A.R./ 22.10.2019