

Notice to Skippers no. 15/20.02.2020

regarding the modifications of the luminous floating and coastal signalling

For the information of the skippers of vessels and convoys, we let you know the modifications operated at the luminous floating and coastal signaling

River Sector of the Danube

1. Km 251+500 green buoy missing since 19.02.2020
2. Km 252+200 Electric Green Buoy missing since 17.02.2020

The present Notice to Skippers modifies the following NtS:

- NtS.15/18.02.2019 pos.1.

General Manager
Sorin Cretu

Chief Engineer
Corneliu Carp

Chief of Hydro-technical, Hydrology
& Danube Commission Department
Mihai Popescu - Teclu

Drafted: C.C./ 1 ex.20.02.2020

Translated: A.R./ 20.02.2020